Technical University of Munich

Fracture, Failure and Fortitude: A Multidisciplinary Analysis of the Japan Air Lines Flight 123 Accident (12 August 1985)

by

Dominic Namachila

July 2024

Abstract

On 12 August 1985, Japan Air Lines (JAL) Flight 123, a Boeing 747SR-46 on a domestic service from Tokyo Haneda to Osaka Itami, suffered an explosive decompression twelve minutes after departure. The failure of the aft pressure bulkhead destroyed most of the vertical stabiliser, severed the auxiliary power unit mounts and ruptured all four hydraulic systems. The crew kept the aircraft in controlled flight for approximately thirty-two minutes using differential engine thrust before it struck a ridge in Gunma Prefecture. Of the 524 people on board, 520 died. It remains the deadliest single-aircraft accident in aviation history.

This thesis presents a multidisciplinary re-examination of the accident. Using the official report of the Aircraft Accident Investigation Commission (AAIC) of Japan as its principal evidence base, together with the published literature on fatigue and fracture, flight dynamics, human performance, search and rescue, and organisational accident causation, it addresses five research questions concerning the technical failure mechanism, the latent organisational conditions that allowed it, the flight-dynamic and human-performance aspects of the post-failure flight, the emergency response, and the lasting influence of the accident on aviation safety.

The analysis shows that the accident cannot be reduced to a single faulty repair. A defective splice made after a 1978 tail strike created a fatigue-critical site; the damage tolerance concept, repair quality assurance, inspection methods and regulatory oversight each failed to expose it over roughly 12,300 flights; and the aircraft's flight-control architecture allowed a single structural event to remove all hydraulic power. Applying Reason's defences-in-depth model, a Systems-Theoretic (STAMP/CAST) control-structure analysis and the concept of drift into failure, the thesis identifies recurring weaknesses in repair assurance and in the independence of safety-critical systems, and argues that the crew's performance, though extraordinary, could not compensate for a design that offered no recourse once the hydraulics were lost. The thesis concludes with recommendations for repair certification, structural-health monitoring, system segregation, emergency-response doctrine and the preservation of accident knowledge within organisations.

Keywords: JAL 123; Boeing 747SR; aft pressure bulkhead; fatigue; improper repair; loss of hydraulics; differential thrust; accident investigation; organisational accident; search and rescue.

Contents

Chapter 1. Introduction **10**

1.1 Background and motivation 10

1.2 Statement of the problem 10

1.3 Aim and objectives 10

1.4 Research questions 11

1.5 Scope and limitations 11

1.6 Significance 11

1.7 Summary data and structure of the thesis 11

Chapter 2. Literature Review **13**

2.1 Theories of accident causation 13

2.2 Fatigue, fracture and damage tolerance in pressurised fuselages 13

2.3 Loss of flight controls and the handling of damaged aircraft 14

2.4 Human performance, crew resource management and culture 14

2.5 Emergency response and survivability 14

2.6 Accident investigation and institutional learning 15

2.7 Research gap 15

Chapter 3. Research Methodology **16**

3.1 Research design 16

3.2 Sources of evidence 16

3.3 Analytical frameworks 16

3.4 Validity, reliability and ethics 16

Chapter 4. The Aircraft, the Operator and the Regulatory Context **18**

4.1 The Boeing 747SR 18

4.2 The aft pressure bulkhead and its surroundings 18

4.3 The operator and the industry context 18

4.4 Regulatory framework 18

Chapter 5. The Accident Flight: Reconstruction **20**

5.1 Pre-flight and departure 20

5.2 The structural failure 20

5.3 Thirty-two minutes of flight without hydraulics 20
5.4 The final minutes and impact 20

Chapter 6. Engineering Analysis of the Structural Failure 22

6.1 The 1978 tail strike and its repair 22
6.2 Fatigue crack growth: an illustrative analysis 22
6.3 Multiple-site damage and the link-up of cracks 23
6.4 Why the cracks were not found 23
6.5 The failure sequence and its consequences 24
6.6 Summary of findings for RQ1 24

Chapter 7. Flight Dynamics and Crew Performance after the Failure 25

7.1 Loss of stability and control 25
7.2 Control by engine thrust 25
7.3 Crew actions 25
7.4 Human factors and CRM 26
7.5 The cabin 26
7.6 Summary of findings for RQ3 26

Chapter 8. Emergency Response and Survivability 27

8.1 Location of the wreckage 27
8.2 The delayed rescue 27
8.3 Survivability analysis 27
8.4 Lessons for emergency planning 27
8.5 Summary of findings for RQ4 27

Chapter 9. The Investigation and its Legal and Institutional Aftermath 29

9.1 The AAIC investigation 29
9.2 Recommendations and responses 29
9.3 Legal and corporate consequences 29
9.4 Persistent controversies and alternative theories 29
9.5 Institutional change 30

Chapter 10. Systemic Analysis 31

10.1 Defences-in-depth analysis 31
10.2 STAMP/CAST analysis 31

10.3 Drift into failure 32
10.4 Summary of findings for RQ2 32

Chapter 11. Lessons, Legacy and Recommendations **33**

11.1 Structural integrity and repair assurance 33
11.2 System independence and control after hydraulic loss 33
11.3 Organisational memory and safety culture 33
11.4 Public memory 33
11.5 Recommendations 33

Chapter 12. Conclusions **35**

12.1 Answers to the research questions 35
12.2 Contributions 35
12.3 Limitations 35
12.4 Future research 35

References **37**

Appendix A. Principal Events Chronology **38**

Appendix B. Notes on Sources and Verification **39**

List of Figures and Tables

Figure 5.1 Timeline of the accident flight

Figure 6.1 Schematic comparison of fatigue crack growth for an improper and a correct repair

Figure 10.1 Defences-in-depth (Swiss cheese) representation of the accident

Table 1.1 Summary data of the accident

Table 3.1 Analytical frameworks and the research questions they serve

Table 6.1 Illustrative sensitivity of fatigue life to local stress amplification

Table 10.1 STAMP/CAST summary of control flaws

Table A.1 Principal events chronology

List of Abbreviations

Abbreviation	Meaning
AAIC	Aircraft Accident Investigation Commission (Japan); succeeded by the Japan Transport Safety Board (JTSB) in 2008
APU	Auxiliary power unit
ATC	Air traffic control
CAST	Causal Analysis based on Systems Theory
CRM	Crew resource management
CVR / FDR	Cockpit voice recorder / flight data recorder
FAA / NTSB	Federal Aviation Administration / National Transportation Safety Board (United States)
ICAO	International Civil Aviation Organization
JCAB	Japan Civil Aviation Bureau
JAL	Japan Air Lines
MSD	Multiple-site damage
SAR	Search and rescue
STAMP	Systems-Theoretic Accident Model and Processes

Chapter 1. Introduction

1.1 Background and motivation

Aviation safety has improved by orders of magnitude since the introduction of the jet airliner, yet progress has often been bought with specific, painful lessons. The accident of Japan Air Lines Flight 123 on 12 August 1985 is among the most instructive. It combined a structural failure of a kind that engineers had in principle learned to prevent after the de Havilland Comet accidents of 1954, an organisational and regulatory failure to detect a defective repair that had been in service for seven years, a catastrophic loss of all hydraulic flight-control power, and a rescue operation whose delays remain a matter of public controversy in Japan.

The accident took place at the height of the Obon holiday travel period, on one of the busiest domestic routes in the world. The aircraft, a high-capacity Boeing 747SR (short range) operated by Japan's flag carrier, carried 509 passengers and 15 crew. Four passengers survived. The accident is frequently cited in numerical terms, as the deadliest accident involving a single aircraft, but its significance for safety science lies in the way it exposes the interaction of engineering, organisational and human factors across a period of seven years.

1.2 Statement of the problem

The official investigation identified the immediate cause: the failure of the aft pressure bulkhead through fatigue cracking that originated at an improperly repaired region. However, the explanation of why a defective repair could pass acceptance, remain undetected through multiple scheduled inspections, and then cause the loss of every hydraulic system on a four-engined wide-body aircraft requires a wider lens. The literature on this accident is divided between technical accounts focused on the structural failure and journalistic or popular accounts focused on the human drama. Few studies integrate structural mechanics, flight dynamics, human performance, emergency response and organisational analysis within a single, coherent framework. This thesis aims to fill that gap.

1.3 Aim and objectives

The aim of this research is to provide an integrated, evidence-based account of the JAL 123 accident that explains how it happened, why the system's defences failed, and what the accident teaches for the design, maintenance and oversight of transport aircraft. The specific objectives are:

- to reconstruct the accident sequence from the official investigation report and supporting literature;
- to analyse the structural failure mechanism using the principles of fatigue and fracture mechanics;

- to analyse the aircraft's handling after the loss of hydraulic power and the performance of the flight crew;
- to evaluate the emergency response and its consequences for survivability;
- to identify latent organisational, regulatory and design factors using established accident-causation models; and
- to derive lessons and recommendations of continuing relevance.

1.4 Research questions

- **RQ1.** What was the technical mechanism of the structural failure, and how did the 1978 repair contribute to it?
- **RQ2.** Which latent conditions in design, maintenance, inspection and oversight allowed the defect to persist for approximately 12,300 flights?
- **RQ3.** How did the loss of the vertical stabiliser and of all hydraulic systems affect the controllability of the aircraft, and how did the crew respond?
- **RQ4.** How did the emergency response affect the outcome for survivors?
- **RQ5.** What lessons from the accident have been adopted, and what remains unresolved?

1.5 Scope and limitations

The study is a retrospective analysis based on publicly available material. It does not involve new access to physical evidence, and it treats the findings of the AAIC as the authoritative factual baseline while noting where later commentary has questioned or supplemented them. Quantitative figures such as flight hours, cycle counts and fatigue-life estimates are reported as published in the literature and should be verified against the primary report before citation. The modelling in Chapter 6 is intended as an illustrative demonstration of mechanisms, not as a reconstruction of the original engineering calculations.

1.6 Significance

The thesis contributes (i) an integrated causal account across technical and organisational layers; (ii) a systems-theoretic control-structure analysis not previously applied in a consolidated form to this accident; (iii) a set of transferable recommendations on repair assurance and system independence; and (iv) a discussion of how safety knowledge is preserved, and sometimes lost, within organisations.

1.7 Summary data and structure of the thesis

Table 1.1 Summary data of the accident

Item	Detail
Date	12 August 1985
Operator / flight	Japan Air Lines, flight JL123
Aircraft	Boeing 747SR-46, registration JA8119 (delivered 1974)
Route	Tokyo Haneda to Osaka Itami (domestic)
Occupants	524 (509 passengers, 15 crew)
Fatalities / survivors	520 / 4
Departure	approx. 18:12 JST
Structural failure	approx. 18:24 JST, about 12 minutes after departure, in the climb near 24,000 ft
Impact	approx. 18:56 JST, ridge of Mount Osutaka, Ueno Village, Gunma Prefecture
Principal cause (official)	Fatigue failure of the aft pressure bulkhead originating at a defective repair made after a 1978 tail strike
Investigating body	Aircraft Accident Investigation Commission (AAIC), Ministry of Transport, Japan
Final report	19 July 1987

Chapter 2 reviews the relevant literature. Chapter 3 sets out the methodology. Chapter 4 describes the aircraft, the operator and the regulatory context. Chapter 5 reconstructs the accident flight. Chapter 6 analyses the structural failure. Chapter 7 treats flight dynamics and crew performance. Chapter 8 examines the emergency response. Chapter 9 reviews the investigation and its legal and institutional aftermath. Chapter 10 applies systemic models of accident causation. Chapter 11 discusses lessons and legacy, and Chapter 12 concludes.

Chapter 2. Literature Review

2.1 Theories of accident causation

Modern accident analysis rests on the recognition that failures in complex systems seldom have a single cause. Reason (1990, 1997) proposed the defences-in-depth, or Swiss cheese, model, in which an accident occurs when latent weaknesses in successive layers of defence line up with an active failure. Perrow (1984) argued that systems that are both tightly coupled and interactively complex will experience "normal accidents" arising from unanticipated interactions. Rasmussen's model of migration toward the boundary of acceptable performance, developed by Dekker (2011) as drift into failure, explains how production and cost pressures can slowly erode safety margins without any single identifiable breach of rules. Leveson (2011) reframed safety as a control problem: accidents result from inadequate enforcement of safety constraints in a hierarchical socio-technical control structure, an idea operationalised in STAMP and the CAST analysis method. Vaughan's (1996) study of the Challenger launch decision introduced the "normalisation of deviance", the process by which anomalies become accepted.

These frameworks are not mutually exclusive. The swiss-cheese model is particularly useful for identifying the layers of defence that failed, STAMP for examining the control relationships among manufacturer, operator and regulator, and drift-into-failure for understanding temporal degradation. This thesis uses all three, as explained in Chapter 3.

2.2 Fatigue, fracture and damage tolerance in pressurised fuselages

The scientific basis of fatigue-crack growth was placed on a quantitative footing by Paris and Erdogan (1963), who showed that, over a wide range, the rate of crack growth per load cycle depends on the range of the stress-intensity factor. Textbook treatments are provided by Broek (1986) and Schijve (2009). The practical lesson was learned at great cost when two Comet 1 airliners broke up in flight in 1954; the subsequent investigation, including water-tank fatigue testing of a complete fuselage, established that cracks had initiated at stress concentrations near the cut-outs and rivet holes of the pressure cabin (Withey, 1997). Out of this experience came the fail-safe and later damage-tolerance design philosophies, which require that a structure can sustain damage, and that the damage can be detected, before it reaches critical size.

A further development concerns multiple-site damage (MSD), in which numerous small cracks form simultaneously at adjacent fastener holes and link up, so that detection and growth predictions for a single dominant crack become unreliable. The 1988 fuselage failure of Aloha Airlines Flight 243, a Boeing 737 (NTSB, 1989), is the best-known example and led to major programmes on ageing aircraft. JAL 123 is a precursor to this discussion: the bulkhead failure was caused by multiple fatigue cracks along a row of rivet holes in a

repaired region.

Repair design deserves particular attention. A repair introduces a new load path, new fastener holes and new stress concentrations. If the repair is not designed and executed to restore the original fatigue performance, the repaired area can become the most fatigue-critical location in the structure, while remaining invisible to inspections designed for the original structure. The literature on repair assurance emphasises engineering approval of the repair scheme, verification of execution against the scheme, and dedicated inspection requirements for repaired areas.

2.3 Loss of flight controls and the handling of damaged aircraft

Transport aircraft are designed so that no single failure, and no reasonably probable combination of failures, should be catastrophic. Hydraulic systems powering the flight controls are therefore duplicated or quadruplicated. Common-mode events, such as an uncontained engine failure or a structural rupture that severs all lines in a shared area, defeat this redundancy. United Airlines Flight 232 (a DC-10 at Sioux City, 1989) lost all three hydraulic systems after the disintegration of the tail-mounted engine; the crew used differential thrust to reach the airport, and 184 of 296 occupants survived (NTSB, 1990). The 2003 attack on a DHL Airbus A300 near Baghdad again showed that an aircraft without hydraulics can be controlled, imperfectly, through engine power. NASA subsequently developed and flight-tested propulsion-controlled aircraft concepts (Burcham et al., 1996). The pioneering case, however, was JAL 123, whose crew performed this feat in 1985, in an aircraft that had also lost most of its vertical stabiliser.

2.4 Human performance, crew resource management and culture

Crew resource management (CRM) emerged in the late 1970s and 1980s in response to accidents in which technically competent crews failed to coordinate effectively. Helmreich and Merritt (1998) documented how national and organisational culture shapes attitudes to command, communication and error. Hofstede's (2001) dimensions, notably power distance, have often been invoked in discussions of Japanese aviation, though such cultural generalisations must be applied with caution. For JAL 123 the relevant human-performance question is not one of conventional error, but of the performance of a crew managing an unprecedented emergency with severely degraded control authority.

2.5 Emergency response and survivability

The survival of occupants after an impact depends on crash forces, the integrity of the occupiable volume, fire, and the time to medical care. The literature on search and rescue emphasises early location of the wreckage, rapid access, and the coordination of civil and military assets, all of which are difficult in mountainous terrain at night. The JAL 123 case is one in which post-impact survival of some occupants has been supported by survivor

testimony, which makes the speed of the rescue a legitimate question for analysis.

2.6 Accident investigation and institutional learning

Annex 13 to the Convention on International Civil Aviation (ICAO) sets the international framework for the independent investigation of accidents, whose sole purpose is accident prevention rather than the apportionment of blame. In Japan the AAIC was established in the 1970s within the Ministry of Transport, and was replaced in 2008 by the Japan Transport Safety Board. The relationship between the safety investigation and criminal or civil proceedings is a continuing source of tension in many jurisdictions and is relevant to the legal aftermath of JAL 123 discussed in Chapter 9.

2.7 Research gap

Existing studies of the JAL 123 accident are mostly either engineering-focused or narrative in character. There is a lack of work that (a) integrates the structural, flight-dynamic, human and organisational analyses, (b) applies a systems-theoretic control-structure analysis to the manufacturer-operator-regulator network, and (c) traces how lessons from the accident were, or were not, institutionalised. This thesis addresses these gaps.

Chapter 3. Research Methodology

3.1 Research design

The research is a retrospective, single-case study with an embedded multi-method analysis. The case study is an appropriate design where the phenomenon is complex, the boundaries between phenomenon and context are indistinct, and multiple sources of evidence are available. The study is explanatory in nature: it seeks to explain how and why the accident occurred, not to test a statistical hypothesis.

3.2 Sources of evidence

- **Primary official material:** the final report of the AAIC (Report No. 62-2, 19 July 1987), including its analyses of the structure, the flight recorders and the aircraft's trajectory.
- **Technical literature:** fracture mechanics, fatigue and damage tolerance texts and papers; reports on comparable accidents (Aloha 243, United 232).
- **Safety science literature:** accident causation, human factors and organisational studies.
- **Secondary and documentary sources:** published survivor and family accounts, journalism, and Japanese-language works, used with attention to provenance and bias.
- **Institutional material:** published information from the operator's safety education programme and memorial sites.

3.3 Analytical frameworks

Table 3.1 Analytical frameworks and the research questions they serve

Framework	Purpose	Research question
Chronological reconstruction	Establish the event sequence and timing	RQ1, RQ3, RQ4
Fracture-mechanics reasoning (Paris-law sensitivity analysis)	Explain how a local defect shortens fatigue life	RQ1
Flight-dynamics reasoning	Explain controllability after loss of the fin and hydraulics	RQ3
Swiss-cheese (defences-in-depth) analysis	Identify failed layers of defence	RQ2
STAMP / CAST control-structure analysis	Identify control flaws among manufacturer, operator, regulator	RQ2, RQ5
Drift into failure	Examine temporal erosion of safety margins	RQ2

3.4 Validity, reliability and ethics

Construct validity is supported by the use of multiple sources and by explicit reference to the official findings. Because the study relies on published material, the main threats are secondary-source error and hindsight bias. To mitigate hindsight bias, the analysis distinguishes between what was knowable at the time of the repair, the inspections and the flight, and what became known only after the accident. The research involves no human participants. Given the scale of the loss, the thesis treats the victims, survivors and families with respect, avoids sensationalism and does not reproduce private communications of the deceased beyond what is already in the public record.

Chapter 4. The Aircraft, the Operator and the Regulatory Context

4.1 The Boeing 747SR

The Boeing 747SR was a variant of the 747 developed for the Japanese domestic market, where very short, high-density routes between the major cities generate a very large number of flights, and therefore of pressurisation cycles, per year. The SR (short range) version featured structural strengthening to cope with the greater fatigue exposure of short-haul operation and could be configured with high-density seating for well over 500 passengers. The aircraft involved, JA8119, a 747SR-46 delivered to JAL in 1974, had by the time of the accident flown roughly 25,000 hours and approximately 18,800 flights.

4.2 The aft pressure bulkhead and its surroundings

The aft pressure bulkhead is a dome-shaped membrane at the rear of the pressurised fuselage. It separates the pressurised cabin from the unpressurised tail cone, which contains the auxiliary power unit and through which hydraulic lines pass on their way to the vertical stabiliser, rudder and horizontal tail. In cruise the pressure differential across the bulkhead is of the order of several pounds per square inch; each flight applies one pressurisation cycle. A rupture of this component therefore combines two effects: a sudden decompression of the cabin and a blast of high-pressure air into the unpressurised tail structure, which is not designed to withstand it.

4.3 The operator and the industry context

Japan Air Lines was established in 1951 and, after a period as a state-owned corporation, was privatised in stages, with the process completed in 1987, the year in which the accident report was published. In the 1980s the Tokyo-Osaka corridor was one of the busiest air routes in the world, and domestic traffic grew rapidly. Such growth places pressure on maintenance capacity and aircraft availability. Whether, and how far, such pressure affected maintenance quality in this case is not established in the official report, and this thesis treats it as a contextual factor that is consistent with, but not proved by, the evidence.

4.4 Regulatory framework

Airworthiness oversight in Japan was exercised by the Civil Aviation Bureau (JCAB) of the Ministry of Transport, while the aircraft type was certified by the Federal Aviation Administration of the United States, the state of design. This split is standard: the state of design is responsible for type certification and continued airworthiness of the design, while the state of registry oversees the maintenance and operation of individual aircraft. Major repairs to a type-certificated structure require approved data. In the case of JA8119 the 1978 repair was carried out by the manufacturer's personnel, which has implications for the

allocation of responsibility explored in Chapters 9 and 10.

Chapter 5. The Accident Flight: Reconstruction

5.1 Pre-flight and departure

Flight JL123 was scheduled to depart Tokyo Haneda for Osaka Itami at 18:00 on 12 August 1985, the Monday on which many Japanese were travelling home for the Obon festival. Departure was slightly delayed, and the aircraft took off at about 18:12 with 524 people on board. The flight deck crew consisted of a captain, a first officer who was in training for upgrade to captain, and a flight engineer, all experienced. Twelve cabin crew served the passengers. The scheduled flight time was about one hour.

5.2 The structural failure

About twelve minutes after take-off, as the aircraft climbed through approximately 24,000 feet over Sagami Bay, there was a loud noise and an immediate rapid decompression. The aft pressure bulkhead had ruptured. The escaping cabin air pressurised the tail cone, causing extensive damage: the APU was torn from its mounts, the greater part of the vertical stabiliser and rudder broke away, and the four independent hydraulic systems, whose lines ran through the affected region, lost their fluid. Passengers described a sudden fogging of the cabin, a rapid fall in pressure and oxygen masks dropping from the ceiling. The crew set the transponder to the emergency code 7700 and declared an emergency, initially requesting to return to Haneda.

5.3 Thirty-two minutes of flight without hydraulics

Following the failure the aircraft was effectively without conventional control of its rudder, elevators, ailerons and spoilers. It exhibited two characteristic uncontrolled motions: a lightly damped long-period pitch oscillation (the phugoid) in which altitude and speed trade against each other over a period of tens of seconds, and, because the fin was lost, a poorly damped Dutch roll combining yaw and roll. The crew discovered that varying the thrust of the engines individually and collectively gave some control over roll, heading and pitch, albeit with a long delay. They extended the landing gear and later the flaps by alternate means, which is reported to have helped damp the oscillations. The aircraft flew an irregular course, turned away from Tokyo toward the mountains of Yamanashi and Gunma, and at times gained and lost thousands of feet. Offers of assistance and suggestions of alternative airfields were made by air traffic control and by the military airfield at Yokota, but the crew's ability to manoeuvre to any runway was severely limited.

5.4 The final minutes and impact

In the final minutes the aircraft descended in the mountain terrain, with the crew trying to keep it in the air. At about 18:55 it struck trees on a ridge, then the main ridge of Mount Osutaka in Ueno Village, Gunma Prefecture. The aircraft disintegrated and a fire broke out

in parts of the wreckage. The rear fuselage section, which carried the four survivors, separated and came to rest on a steep slope.




Figure 5.1 Timeline of the accident flight (times JST; positions approximate; after the AAIC report as interpreted by the author)

The tape recorders confirm that, throughout the emergency, the flight deck crew continued to perform standard calls, worked as a team, and, according to the transcript, sustained attempts to control the aircraft until the end. A full chronology appears in Appendix A.

Chapter 6. Engineering Analysis of the Structural Failure

6.1 The 1978 tail strike and its repair

On 2 June 1978, the same aircraft suffered a tail strike while landing at Osaka Itami, scraping the rear fuselage on the runway. The damage included deformation of the aft pressure bulkhead. The manufacturer was engaged to carry out the repair. Because a large part of the lower bulkhead was damaged, the repair involved replacing the lower half of the bulkhead skin and joining it to the retained upper part along a horizontal splice.

The approved procedure called for a continuous splice plate with three rows of rivets on each side of the joint, so that the load would be transferred smoothly across the splice. The repair as executed instead used splice plates that were cut into two sections, and over part of the length the joint was held by only a single row of rivets. The reduced fastener pattern concentrated load into fewer fasteners and raised the local stress amplitude at those rivet holes. The investigation attributed the accident to fatigue cracks that grew from this region. Commonly cited estimates, which should be checked against the primary report, indicate that the faulty splice had approximately 70 per cent of the fatigue strength of a correct repair and a fatigue life far shorter than the planned service life of the structure.

6.2 Fatigue crack growth: an illustrative analysis

For a crack of length a subject to a cyclic stress range $\Delta\sigma$, the stress-intensity-factor range is $\Delta K = Y\Delta\sigma\sqrt{(\pi a)}$, where Y is a geometry factor. The Paris-Erdogan law states that the crack growth per cycle is $da/dN = C(\Delta K)^m$, with C and m material constants; for aluminium alloys m is typically between about 3 and 4. Integrating from an initial crack size a_0 to a critical size a_c gives, for $m \neq 2$, the number of cycles $N_f = [a_c^{1-m/2} - a_0^{1-m/2}] / [C(Y\Delta\sigma\sqrt{\pi})^m(1 - m/2)]$.

The important feature of this result is that the life varies inversely with the m-th power of the stress range. A modest local increase in stress, caused for example by carrying the load through fewer rivets, therefore produces a disproportionate reduction in life. Table 6.1 shows this effect for an assumed $m = 3$.

Table 6.1 Illustrative sensitivity of fatigue life to local stress amplification (assumed Paris exponent m = 3; calculated as 1/factor^3; illustrative only)

Local stress amplification factor	Remaining life as fraction of baseline (m = 3)
1.0 (correct design)	1.00
1.1	0.75
1.2	0.58
1.3	0.46
1.4	0.36
1.5	0.30

These figures are not claimed to reproduce the actual calculation, which would require the real joint geometry and load spectrum, but they illustrate why a seemingly small departure from the approved fastener pattern could shorten the life of the structure from many tens of thousands of flights to one that was exceeded by the actual service history of the aircraft: about 12,300 flights elapsed between the repair and the failure.




Figure 6.1 Schematic comparison of fatigue crack growth for an improper and a correct repair (qualitative; not to scale; the 12,300-flight marker is the reported interval between repair and failure)

6.3 Multiple-site damage and the link-up of cracks

The cracks in the bulkhead were not isolated. Fatigue cracks developed at several rivet holes along the single-row region. As adjacent cracks approached each other, the ligaments between them failed and the cracks linked into a longer crack, which accelerates growth because the stress-intensity factor rises with crack length. At a critical stage the remaining structure could no longer carry the pressure load and the bulkhead failed rapidly. The dynamics of MSD make it unsafe to assume a long period of stable, detectable growth: once cracks are numerous the interval between the moment the damage becomes detectable and the moment it becomes critical can be short.

6.4 Why the cracks were not found

A damage-tolerant structure is only as safe as the inspection programme that accompanies it. The cracks in JA8119 initiated at the faying surface and rivet holes in the area covered by the splice plate, where they were hidden from visual inspection. The inspection regime in force was designed for the original structure and did not provide a dedicated, effective means of finding cracks beneath the repair. The aircraft had passed several scheduled maintenance checks since the repair without the defect being recognised. This is a classic instance of the failure of the second line of defence: inspection is intended to catch precisely those faults that design and workmanship have let through.

6.5 The failure sequence and its consequences

When the bulkhead ruptured, the pressure differential drove cabin air into the tail cone at a rate far exceeding the capacity of the tail structure's venting. The resulting overpressure destroyed the structure of the tail cone and the base of the vertical stabiliser, removing most of the fin and rudder, and damaged the APU. The four hydraulic systems each lose their fluid if their lines are severed, and in this case their routing through the damaged zone left no independent path. In design-assurance terms, the event was a common-cause failure that defeated redundancy that, on paper, made total loss of hydraulic power extremely improbable.

6.6 Summary of findings for RQ1

The technical mechanism was the fatigue failure of the aft pressure bulkhead, originating at multiple cracks in a region repaired with a defective splice. The repair is the proximate engineering cause, but the failure of the design to be tolerant of the damage, and of the inspection programme to detect it, were necessary conditions for the catastrophic outcome.

Chapter 7. Flight Dynamics and Crew Performance after the Failure

7.1 Loss of stability and control

The vertical stabiliser provides directional (yaw) stability and, through the rudder, yaw control. Its removal leaves an aircraft with little natural resistance to sideslip, so that disturbances produce Dutch roll oscillations. The simultaneous loss of hydraulic power meant that the elevators, ailerons, spoilers, rudder and flaps could not be moved in the normal manner. Pitch behaviour of the unaugmented aircraft is dominated by a long-period phugoid mode, in which the aircraft alternately climbs and slows, then descends and accelerates, with very light damping. Together these modes made the aircraft a highly challenging, and in principle nearly unmanageable, vehicle.

7.2 Control by engine thrust

With the engines mounted on the wings, a difference in thrust between the left and right sides produces a yawing moment, which through the dihedral effect also induces roll, allowing a limited degree of heading control. Collective thrust changes produce pitching moments because the engines are mounted below the aircraft's centre of gravity and because speed changes alter lift. The method is inherently slow and imprecise: engines spool up and down with a delay of several seconds, and the aircraft's response lags further. Subsequent research (Burcham et al., 1996) showed that even trained test pilots find it very difficult to land a transport aircraft using thrust alone.

7.3 Crew actions

Within the limits of the evidence, the flight crew reacted in an orderly way. They took stock of the damage, declared an emergency, tried the available alternate systems, extended the landing gear and flaps by alternate means to improve stability, and used thrust to hold the aircraft in a controlled, if oscillating, flight for more than half an hour. The cockpit voice recorder shows a flight deck that maintained task allocation and communication throughout. The first officer's training status meant that an instructor-trainee relationship existed in the cockpit, but there is no suggestion in the evidence of a failure of coordination.

A frequently debated question is whether the crew could have achieved a landing. Controllability in pitch and roll was so limited, and the aircraft's descent rate and speed so difficult to regulate, that a precision approach to a runway was practically out of reach. The comparison with United 232, which was controllable enough to be directed to a runway with the help of an additional instructor pilot, is instructive: the JAL aircraft had also lost the vertical fin, which made it considerably less stable. The conclusion that the aircraft was effectively uncontrollable for the purpose of landing is therefore consistent with the evidence.

7.4 Human factors and CRM

From a CRM viewpoint, the performance of the crew provides an example of effective leadership, communication and workload management under extreme stress. The thesis concurs with the general view in the safety literature that the crew's performance was exemplary. A caution is needed, however: praise for the crew should not obscure the point that the system had placed them in a position in which the best possible performance could not save the aircraft. Safety must be engineered into the aircraft and the organisation, rather than relying on the exceptional performance of individuals in situations they cannot control.

7.5 The cabin

In the cabin, passengers faced sustained fear for more than half an hour. The emergency procedures of the cabin crew, including the distribution of instructions on brace positions and life jackets, were carried out. Several passengers wrote brief messages to their families on whatever paper was at hand; these documents, preserved and made public, have become among the most poignant records of the accident. One survivor was an off-duty JAL flight attendant travelling as a passenger. The accounts of the four survivors have been an important source of information about conditions in the cabin and about the period after the crash.

7.6 Summary of findings for RQ3

The loss of the fin and of all hydraulics rendered the aircraft barely controllable. The crew's use of differential thrust prolonged the flight and kept the aircraft away from densely populated areas, but a safe landing was not realistically attainable. The most important lesson of the flight-dynamic analysis is the need for designs in which a single structural event cannot remove all control authority.

Chapter 8. Emergency Response and Survivability

8.1 Location of the wreckage

The crash site lay in a rugged, forested mountain area. The darkness, the terrain and the uncertainty about the aircraft's final position complicated the response. Early reports of the position were inconsistent, and some placed the crash in neighbouring Nagano Prefecture. A United States Air Force transport aircraft from Yokota Air Base is reported to have sighted the burning wreckage within about two hours of the crash and relayed its position.

8.2 The delayed rescue

Japanese ground forces and police reached the crash site only in the morning of 13 August, some fifteen hours after the impact, and the four survivors were found and evacuated that day. Survivors and some commentators have claimed that a US military helicopter crew was prepared to attempt a rescue at night and was stood down at the request of the Japanese side. The accuracy of these accounts, and the reasons for the decisions taken on the Japanese side, have been disputed. The thesis does not seek to settle that dispute but notes what is not in contention: the survivors were found long after the crash, some of them reported having heard other occupants alive after the impact, and the response was slower than the importance of the first hours would have demanded.

8.3 Survivability analysis

The structure of the fuselage in the rear section, where the four survivors were seated, was not destroyed to the same extent as the forward sections, and passengers in this section had a higher probability of survival. The injuries of those who died include both impact trauma and, for some, injuries consistent with a period of survival after the impact. Medical opinion on the number who might have been saved by a faster rescue differs, and the question remains unresolved. What is generally accepted is that the speed of response is a decisive factor in survivability in the minutes and hours following a crash.

8.4 Lessons for emergency planning

- Pre-planned procedures for rapid location of wreckage, including the use of all civil and military assets, and clear command responsibilities;
- Capability for night and mountain operations, including the use of airborne rescue assets and a clear protocol for foreign-military assistance;
- Accuracy and speed of communication of position information, and the integration of recorder and radar data into search coordination;
- Regular exercises in difficult terrain with all relevant agencies.

8.5 Summary of findings for RQ4

The emergency response contributed to the outcome by delaying medical care for those who survived the impact. The exact effect on the number of survivors cannot be reconstructed with certainty, but the case is a standing argument for pre-planned, well-exercised rescue doctrine for accidents in remote terrain.

Chapter 9. The Investigation and its Legal and Institutional Aftermath

9.1 The AAIC investigation

The AAIC investigated the accident with the participation of the US National Transportation Safety Board and the manufacturer, in line with ICAO Annex 13. The flight data recorder and cockpit voice recorder were recovered from the wreckage and provided the basis for the reconstruction of the flight. The final report, published on 19 July 1987, concluded that the aft pressure bulkhead had failed from fatigue cracks that began at the improperly repaired region, that the failure of the bulkhead led to the destruction of the tail structure and loss of hydraulic function, and that the inability to control the aircraft resulted in the crash. It further concluded that the inspections following the repair had not detected the cracks.

9.2 Recommendations and responses

The report called for the strengthening of repair procedures and of their verification, for better inspection techniques and intervals for repaired structure and for improved protection of the aircraft's hydraulic systems against damage in the rear fuselage area. Subsequent regulatory developments in aircraft ageing and repair assessment, discussed in Chapter 11, were influenced by this and other accidents of the period.

9.3 Legal and corporate consequences

The accident led to extensive criminal investigation in Japan of the manufacturer, the operator and the authorities for professional negligence resulting in death. In 1990, prosecutors decided not to bring charges, in large part because it was not possible to establish the individual criminal responsibility of identified persons for events many years earlier. The manufacturer acknowledged that its repair had been defective, and compensation was agreed with the families by the operator, with the manufacturer bearing a share. Senior figures at the operator left their posts. The decision not to prosecute left many families dissatisfied, illustrating a persistent difficulty: complex organisational accidents seldom lend themselves to the attribution of individual criminal blame, while the safety value of open investigation depends on participants being willing to speak candidly.

9.4 Persistent controversies and alternative theories

Over the years, alternative explanations of the accident have been advanced, including claims that a missile or drone struck the aircraft or that evidence was concealed. These claims are not supported by the physical evidence, which is consistent with the structural failure documented in the official report, and the thesis does not regard them as credible. They are nonetheless of sociological interest: they reflect the distrust that arises when the response to an accident is perceived as incomplete or secretive, and they underline the

importance of transparent investigation and communication with families.

9.5 Institutional change

The accident had profound institutional effects. It contributed to a reappraisal of safety management in the operator, which was to be subjected to repeated safety challenges in later decades, and eventually led to the creation of the Safety Promotion Center at Haneda in 2006, where parts of the wreckage, including the rear pressure bulkhead and a portion of the vertical stabiliser, are on display and where employees receive safety education. The accident is commemorated annually at a memorial in Ueno Village, where families and others climb to the crash site on the anniversary.

Chapter 10. Systemic Analysis

10.1 Defences-in-depth analysis

Applied to JAL 123, the Swiss-cheese model identifies at least five layers in which latent weaknesses were present (Figure 10.1). First, the design did not provide adequate protection against the combined effects of a bulkhead rupture, which could remove the vertical stabiliser and sever all hydraulic lines. Second, the repair process lacked an effective check that the work conformed to approved data. Third, acceptance and regulatory oversight did not detect the deviation. Fourth, the in-service inspection programme could not find cracks hidden beneath the splice plate. Fifth, the flight-control architecture offered no means of controlling the aircraft after the hydraulic systems were lost.




Figure 10.1 Defences-in-depth (Swiss cheese) representation of the JAL 123 accident (schematic)

10.2 STAMP/CAST analysis

The control-structure perspective shifts attention from components to the relationships among actors. At the top is the state-of-design regulator (FAA), the state-of-registry regulator (JCAB), the manufacturer and the operator; below are the maintenance organisation, the inspectors and the flight crew; at the bottom is the physical system. Table 10.1 summarises identified control flaws.

Table 10.1 STAMP/CAST summary of control flaws

Controller	Safety constraint	Control flaw (as inferred from the evidence)
Manufacturer repair team	Repair must restore structural integrity to approved data	Departure from the approved splice; inadequate verification of execution
Operator (maintenance)	Detect and correct structural deterioration	Inspection programme did not target the repaired area; cracks hidden under the splice not found
State of registry (JCAB)	Ensure repairs and maintenance meet airworthiness standards	Oversight did not detect a non-conforming major repair; feedback on repair quality inadequate
State of design (FAA) / manufacturer design	Design shall tolerate foreseeable damage and independent failures	Hydraulic routing allowed common-mode loss; damage tolerance did not cover a bulkhead failure of this kind
Emergency services	Locate and rescue survivors quickly	Delayed locating and reaching the wreckage; coordination of assets unclear

Common to several of these flaws is inadequate feedback. A repair that has been performed non-conformingly produces no visible signal; the structure simply carries the load until it cannot. Unless the system has designed-in verification (independent inspection of repairs, records of repair conformity, structural-health monitoring), the controllers have no means of knowing that the safety constraint has been violated.

10.3 Drift into failure

The timeline of the aircraft's life shows how a fault can remain latent for years. The repair was completed in 1978 and the aircraft flew intensively for the next seven years, over a period in which JAL's domestic network was growing. Each flight that ended safely provided an apparent confirmation that the structure was sound, and so reinforced the confidence of the organisation. This is the mechanism that Dekker (2011) describes: the absence of failure is mistaken for the presence of safety. The thesis does not claim that deliberate cost-cutting caused the accident; rather, it argues that the system lacked mechanisms that would have prevented the normal pressures of operation from eroding its margins.

10.4 Summary of findings for RQ2

The latent conditions that allowed the defect to persist include (a) non-conformance in the repair and the absence of effective independent verification; (b) an inspection programme not designed for the repaired structure; (c) regulatory oversight with weak feedback on repair quality; and (d) a design in which a single structural failure could remove all hydraulic power. These are failures of system design and control, rather than of an individual, and they could recur in any system that does not address them structurally.

Chapter 11. Lessons, Legacy and Recommendations

11.1 Structural integrity and repair assurance

The accident reinforced the principle that a repair is a design change which must be treated with the same rigour as the original design: it requires approved data, qualified personnel, independent verification, complete records, and a dedicated inspection plan. The Aloha Airlines accident in 1988 led to the ageing aircraft programmes of the FAA and others, which broadened the discussion to include structural repairs and modifications, supplemental inspections and the assessment of widespread fatigue damage. JAL 123 is part of the same historical learning process.

11.2 System independence and control after hydraulic loss

Together with the United 232 accident of 1989, JAL 123 became a standing demonstration that physical segregation of redundant systems is essential, and that redundancy that shares a vulnerable location is redundancy only on paper. Later design practice has given greater emphasis to routing and protection of hydraulic lines, to the use of isolation devices and to electrically powered backup actuation. The NASA research into propulsion-controlled aircraft explored whether flight-control computers could use engine thrust automatically to assist in an emergency.

11.3 Organisational memory and safety culture

Perhaps the most distinctive legacy of the accident is its role in the operator's safety culture. The decision to preserve wreckage for display, to bring employees into direct contact with the evidence and to maintain annual commemoration reflects the recognition that knowledge of an accident fades unless institutions work deliberately to retain it. The thesis suggests that the operator's later experience is relevant: it suffered further safety incidents in the 2000s and a financial collapse in 2010, indicating that the maintenance of safety culture is a continuing task and that a memorial is not a substitute for managerial vigilance.

11.4 Public memory

The accident has become part of Japanese public memory. It has been the subject of books, television documentaries and a well-known novel and film that portray the work of local journalists covering the crash. One of the dead was the singer Kyu Sakamoto, whose song known abroad as "Sukiyaki" was an international hit in 1963. The annual climb to the memorial site, and the public statements of families, continue to keep the questions of accountability and of the rescue on the public agenda.

11.5 Recommendations

- **Repair certification:** require approved data, independent conformity inspection and permanent records for all major structural repairs, with mandatory supplemental inspections targeted at the repaired area.
- **Inspection technology:** develop and apply non-destructive evaluation and structural-health-monitoring methods able to find cracks beneath doublers and splices.
- **Design for common-cause events:** demonstrate through design review that no single structural failure in a defined zone can remove all hydraulic power or flight-control authority, or provide a backup capability that can.
- **Emergency control:** consider the incorporation of thrust-based emergency flight-control augmentation in the flight-control software of new aircraft.
- **Emergency response:** establish pre-agreed procedures, including international mutual aid, for the rapid location and night rescue of survivors in remote terrain.
- **Investigation and learning:** maintain the separation of safety investigation from criminal proceedings to the extent possible, and ensure the involvement of families in transparent communication.
- **Organisational memory:** institutionalise the lessons of accidents in training, in the safety management system and in management decisions.

Chapter 12. Conclusions

12.1 Answers to the research questions

RQ1. The technical mechanism was fatigue failure of the aft pressure bulkhead. A defective splice made after the 1978 tail strike, in which the specified three-row riveted splice was replaced by a configuration that over part of its length used only a single row, raised local stresses and led to multiple fatigue cracks that linked and led to the failure approximately 12,300 flights after the repair.

RQ2. The defect persisted because several layers of defence failed together: the repair was not verified against approved data; the oversight system did not detect the non-conformance; the inspection programme could not find cracks hidden under the splice; and the design permitted a single event to remove all hydraulic power.

RQ3. The loss of the vertical stabiliser and of the hydraulic systems left the aircraft barely controllable. The crew's use of differential thrust prolonged the flight by roughly thirty-two minutes, but a landing could not realistically have been achieved.

RQ4. The emergency response, with its delay in reaching the wreckage, reduced the chances of those who survived the impact, although the exact effect cannot be quantified.

RQ5. The lessons concerning repair assurance, structural inspection, system segregation, emergency response and organisational memory have been absorbed unevenly. Many have been built into regulations and design practice, while others, in particular the preservation of safety knowledge within organisations, require continuing effort.

12.2 Contributions

The thesis integrates technical, human and organisational analyses of a single accident; provides an illustrative quantitative demonstration of the sensitivity of fatigue life to local stress amplification; applies a systems-theoretic control-structure analysis to the manufacturer-operator-regulator network; and derives recommendations of continuing relevance.

12.3 Limitations

The study depends on published sources and not on the primary physical evidence or original recorder data. Figures reported from secondary literature should be verified against the official report. The Paris-law analysis is illustrative and does not reproduce the original engineering calculations. Japanese-language primary material is likely to contain further detail that future work should consult.

12.4 Future research

- A quantitative reconstruction of the fatigue-crack growth using the original structural drawings and the load spectrum, if released;
- A comparative study of repair-related accidents and incidents (including tail-strike repairs) across manufacturers and operators;
- Simulation of thrust-only control of the damaged 747SR and the assessment of the feasibility of automated emergency control;
- Studies of the long-term effects of the accident on survivors, families and the community; and
- Evaluation of the effectiveness of memorial-based safety education in sustaining safety culture.

References

Note to the candidate: all references below should be checked against the originals, and the formatting adjusted to the citation style required by your institution, before submission.

Aircraft Accident Investigation Commission (1987). *Aircraft Accident Investigation Report: Japan Air Lines Co., Ltd., Boeing 747 SR-100, JA8119, Gunma Prefecture, Japan, August 12, 1985* (Report No. 62-2). Tokyo: Ministry of Transport.

Broek, D. (1986). *Elementary Engineering Fracture Mechanics* (4th ed.). Dordrecht: Martinus Nijhoff.

Burcham, F. W., Maine, T. A., Fullerton, C. G., and Wells, L. (1996). *Preliminary Flight Results of a Fly-by-Throttle Emergency Flight Control System on an F-15 Airplane* (NASA Technical Paper 3627). Edwards, CA: NASA Dryden Flight Research Center.

Dekker, S. (2011). *Drift into Failure: From Hunting Broken Components to Understanding Complex Systems*. Farnham: Ashgate.

Helmreich, R. L., and Merritt, A. C. (1998). *Culture at Work in Aviation and Medicine: National, Organizational and Professional Influences*. Aldershot: Ashgate.

Hofstede, G. (2001). *Culture's Consequences: Comparing Values, Behaviors, Institutions and Organizations across Nations* (2nd ed.). Thousand Oaks, CA: Sage.

International Civil Aviation Organization (current edition). *Annex 13 to the Convention on International Civil Aviation: Aircraft Accident and Incident Investigation*. Montreal: ICAO.

Leveson, N. G. (2011). *Engineering a Safer World: Systems Thinking Applied to Safety*. Cambridge, MA: MIT Press.

National Transportation Safety Board (1989). *Aircraft Accident Report: Aloha Airlines, Flight 243, Boeing 737-200, N73711, near Maui, Hawaii, April 28, 1988* (NTSB/AAR-89/03). Washington, DC: NTSB.

National Transportation Safety Board (1990). *Aircraft Accident Report: United Airlines Flight 232, McDonnell Douglas DC-10-10, Sioux Gateway Airport, Sioux City, Iowa, July 19, 1989* (NTSB/AAR-90/06). Washington, DC: NTSB.

Paris, P., and Erdogan, F. (1963). A critical analysis of crack propagation laws. *Journal of Basic Engineering*, 85(4), 528-533.

Perrow, C. (1984). *Normal Accidents: Living with High-Risk Technologies*. New York: Basic Books.

Reason, J. (1990). *Human Error*. Cambridge: Cambridge University Press.

Reason, J. (1997). *Managing the Risks of Organizational Accidents*. Aldershot: Ashgate.

Schijve, J. (2009). *Fatigue of Structures and Materials* (2nd ed.). Dordrecht: Springer.

Vaughan, D. (1996). *The Challenger Launch Decision: Risky Technology, Culture, and Deviance at NASA*. Chicago: University of Chicago Press.

Withey, P. A. (1997). Fatigue failure of the de Havilland Comet I. *Engineering Failure Analysis*, 4(2), 147-154.

Yokoyama, H. (2003). *Climber's High* [novel on the press coverage of the JAL 123 crash]. Tokyo: Bungeishunju.

Appendix A. Principal Events Chronology

Table A.1 Principal events chronology

Date / time (JST)	Event
1974	Boeing 747SR-46 JA8119 delivered to JAL
2 June 1978	Tail strike on landing at Osaka Itami; aft pressure bulkhead damaged
1978	Bulkhead repaired by the manufacturer; splice executed with a reduced fastener pattern over part of its length
1978-1985	Approximately 12,300 flights (pressurisation cycles) following the repair, with scheduled maintenance checks
12 Aug 1985, approx. 18:12	JL123 departs Tokyo Haneda for Osaka Itami
approx. 18:24	Rapid decompression; aft pressure bulkhead fails; vertical fin, APU and hydraulic lines damaged
shortly after	Emergency declared (7700); crew requests to return to Haneda
18:25-18:55	Flight under differential thrust control; gear and flaps extended by alternate means; irregular track toward the mountains
approx. 18:55-18:56	Contact with trees and then the Osutaka ridge, Ueno Village, Gunma
Evening of 12 Aug	Burning wreckage reported sighted from the air; position relayed
13 Aug (morning)	Ground teams reach the site; four survivors rescued
19 July 1987	AAIC final report published
1990	Prosecutors decline to bring criminal charges
2006	JAL Safety Promotion Center opens at Haneda

Appendix B. Notes on Sources and Verification

This thesis is written from the published record and from general engineering and safety-science knowledge. The following items are those which the candidate should verify against the primary AAIC report and, where possible, the Japanese-language originals before final submission:

- exact times of events (decompression, emergency declaration, impact) and the aircraft's flight path and altitudes;
- flight hours and cycle counts for JA8119, and the number of flights between repair and failure;
- the quantitative estimate of the reduction in fatigue strength attributed to the faulty splice;
- the details of the repair design and the as-executed splice configuration;
- details of the sequence and timing of the rescue and of the statements on foreign military assistance;
- the content and wording of the report's recommendations and of subsequent regulatory actions.